

# Intraoperative Images for Miscounts OR Guidance

## STEP 1: Contact the Surgical Imaging Supervisor/Lead

- UAB Main: (205)996-2281 or (205)975-9999
- UAB Highlands: (205) 930-7826 or (205) 930-6742

## STEP 2: Provide Information

- OR room #
- OR call back phone #
- Body part to be imaged
- Miscounted item type

## STEP 3: Imaging Personnel Assigned and Images Performed

The Surgical Imaging Supervisor/ Lead will assign a technologist to perform images.

Note: If a technologist is not available, one will be pulled from an active surgical case at the discretion of the Surgical Imaging Supervisor/Lead.

## STEP 4: Interpretation of Images

The Radiologist will call the OR call back phone # to provide a verbal report.

Please refer to UAB Policy R 48 *Surgical Counts* for more information.